Component Number: 6093R **Where is this used?**

Part Number	Description	Component Quantity	U/M
25355	Model HMC 30 Deg. 2 Motor Tandem System - Red Upper Boots	1.00	EA
28683	Model 75 Intl 30 Deg. 2 Motor Tandem System - Clear Upper Boots	1.00	EA
28684	Model 90 Intl 30 Deg. 2 Motor Tandem System - Clear Upper Boots	1.00	EA
34333	Model 108 Single Straight-Through Tandem System - Red Upper Boots	2.00	EA
34340	Model 108 Straight-Out Boot Assembly - Red Upper Boot	1.00	EA
35616	Model 108 Twin Straight-Through Tandem System - Red Upper Boots	2.00	EA
35626	Model 108 Straight-Out Twin Boot Assembly - Red Upper Boot	1.00	EA
35880	Model 75 Twin Straight-Through Tandem System - Red Upper Boots	2.00	EA
35880SS	Model 75 SS Twin Straight-Through Tandem System - Red Upper Boots	2.00	EA
36795	Model HMC Twin Straight-Through Tandem System - Red Upper Boots	2.00	EA
36795SS	Model HMC SS Twin Straight-Through Tandem System - Red Upper Boots	2.00	EA
36801	Model 75 Twin Straight Out Boot Assembly - Red Upper Boot	1.00	EA
36801SS	Model 75 SS Twin Straight Out Boot Assembly - Red Upper Boot	1.00	EA
38916	Model 90 Twin Straight-Through Tandem System - Clear Upper Boots	2.00	EA
40082	Model HMC Single Straight-through Tandem System - Red Upper Boots	2.00	EA
40082SS	Model HMC SS Single Straight-through Tandem System - Red Upper Boots	2.00	EA
47865	Model 108 Two-Motor Tandem Boot System Kit - Red Upper Boots	2.00	EA
48660	Model 90 3-Bin Twin Straight-Through Tandem System - Red Upper Boots	3.00	EA

56422-1	75 Plus Single Straight-Through Tandem System	2.00	EA
56422-2	BOOT,SINGLE S-O ASSY 75 PLUS	1.00	EA
56422SS-1	75 PLUS SS Single Straight Through Tandem System	2.00	EA
56422SS-2	BOOT,SS SINGLE S-O ASSY 75PLUS	1.00	EA
56424-1	Model 75 PLUS Twin Straight-Through Tandem	2.00	EA
56424-2	BOOT,TWIN S-O ASSY 75 PLUS	1.00	EA
56424SS-1	Model 75 PLUS SS Twin Straight-Through Tandem	2.00	EA
56424SS-2	BOOT,SS TWIN S-O ASSY 75 PLUS	1.00	EA
6187	Model 90 Straight-Out Single Boot Assembly - Red Upper Boot	1.00	EA
6187EUR	Model 90 Straight-Out Boot Assembly - Red Upper Boot	1.00	EA
6187SS	Model 90 SS Straight-Out Single Boot Assembly - Red Upper Boot	1.00	EA
6281	Model 90 Single Straight-through Tandem System - Red Upper Boots	2.00	EA
6281EUR	Model 90 Eur Single Straight-Through Tandem System - Red Upper Boots	2.00	EA
6281SS	Model 90 SS Single Straight-through Tandem System - Red Upper Boots	2.00	EA
6535	Model 90 Twin Straight Out Boot Assembly - Red Upper Boot	1.00	EA
6535EUR	Model 90 Twin Straight Out Boot Assembly	1.00	EA
6535SS	Model 90 SS Twin Straight Out Boot Assembly - Red Upper Boot	1.00	EA
6538	Model 90 Twin Straight-Through Tandem System - Red Upper Boots	2.00	EA
6538EUR	Model 90 Europe Twin Straight-through Tandem System - Red Upper Boots	2.00	EA
6538SS	Model 90 SS Twin Straight-Through Tandem System - Red Upper Boots	2.00	EA
6540	Model 75 Straight-Out Single Boot Assembly - Red Upper Boot	1.00	EA
6540SS	Model 75 SS Straight-Out Single Boot Assembly - Red Upper Boot	1.00	EA

6541	Model 75 Single Straight-Through Tandem System - Red Upper Boots	2.00	EA
6541SS	Model 75 SS Single Straight-Through Tandem System - Red Upper Boot	2.00	EA
7881	Model 75 30 Deg. 2 Motor Tandem System - Red Upper Boots	1.00	EA
7882-1	Model 90 30 Deg. 2 Motor Tandem 216RPM System - Red Upper Boots	1.00	EA
7882-2	Model 90 30 Deg. 2 Motor Tandem 348RPM System - Red Upper Boots	1.00	EA
7883	Model 75 International 30 Deg. 2 Motor Tandem System - Red Upper Boots	1.00	EA
7884	Model 90 International 30 Deg. 2 Motor Tandem System - Red Upper Boots	1.00	EA