Component Number: 3531 **Where is this used?**

Part Number	Description	Component Quantity	U/M
24291	Model 90 Lower Boot Assembly	1.00	EA
34803	Boot Assembly Agitator	1.00	EA
36389	Model 75 30 Degree Twin Lower Boot Assembly	2.00	EA
36389SS	Model 75 SS 30 Degree Twin Lower Boot Assembly	2.00	EA
36390	Model 75 Twin Straight Out Lower Boot Assembly	2.00	EA
36390SS	Model 75 Twin Straight Out Lower Boot Assembly (Stainless Steel)	2.00	EA
36391	Model 90 30 Degree Twin Lower Boot Assembly	2.00	EA
36391EUR	Model 90 30 Degree Twin Lower Boot Assembly	2.00	EA
36391SS	Model 90 30 Degree Twin Lower Boot Assembly (Stainless Steel)	2.00	EA
36398	Model 90 Twin Straight Out Lower Boot Assembly	2.00	EA
36398EUR	Model 90 Twin Straight Out Lower Boot Assembly	2.00	EA
36398SS	Model 90 Twin Straight Out Lower Boot Assembly (Stainless Steel)	2.00	EA
36434	Model 90 Straight-Through Tandem Lower Boot Package	2.00	EA
36434EUR	Model 90 Europe Straight-Through Tandem Lower Boot Package	2.00	EA
36434SS	Model 90 SS Straight-Through Tandem Lower Boot Package	2.00	EA
36435	Model 90 Straight-Out Lower Boot Assembly	1.00	EA
36435EUR	Model 90 Straight-Out Lower Boot Assembly	1.00	EA
36435SS	Model 90 Straight-Out Lower Boot Assembly (Stainless Steel)	1.00	EA
36442	Model 75 Lower 30 Degree Boot Assembly	1.00	EA

36442SS	Model 75 Lower 30 Degree Boot Assembly (Stainless Steel)	1.00	EA
36589	Model 75 Straight-Out Lower Boot Assembly	1.00	EA
36589SS	Model 75 Straight-Out Lower Boot Assembly (Stainless Steel)	1.00	EA
36590	Model 75 Straight-Through Tandem Lower Boot Package	2.00	EA
36590SS	Model 75 SS Straight-Through Tandem Lower Boot Package	2.00	EA
38506	Model HMC Twin Lower Boot Assembly	2.00	EA
38506SS	Model HMC Twin Lower Boot Assembly (Stainless Steel)	2.00	EA
38507	Model HMC Lower Boot Assembly	1.00	EA
38507SS	Model HMC Lower Boot Assembly (Stainless Steel)	1.00	EA
38605	Model HMC 30 Degree Two Motor Tandem Boot Assembly - Red Upper Boots	1.00	EA
38606	Model HMC Boot Assembly	1.00	EA
40081	Model HMC Straight Through Tandem Lower Boot Package	2.00	EA
40081SS	Model HMC Straight Through Tandem Lower Boot Package (Stainless Steel)	2.00	EA
56386	BOOT,SINGLE 30DEG LOWER ASSY	1.00	EA
56386SS	BOOT,SS SINGLE 30DEG LWR ASSY	1.00	EA
56389	BOOT,SINGLE S-O LWR ASSY 75	1.00	EA
56389SS	BOOT,SS SINGLE S-O LWR ASSY 75	1.00	EA
56419	BOOT,TWIN 30DEG LWR ASSY 75	2.00	EA
56419SS	BOOT,SS TWIN 30DEG LWR ASSY	2.00	EA
56421	BOOT,TWIN S-O LWR 75 PLUS	2.00	EA
56421SS	BOOT,SS TWIN S-O LWR 75 PLUS	2.00	EA
56423	PKG,SINGLE S-T TNDM LWR BOOT	2.00	EA
56423SS	75 PLUS SS Single Straight-Through Tandem Boot Package	2.00	EA
56470	Model 75 Plus Extension Boot Assembly	1.00	EA
56470SS	Model 75 Plus Extension Boot Assembly (Stainless Steel)	1.00	EA

57310	ATF Twin Boot Assembly	2.00	EA
6669R	Baffle Replacement With Decal 90	1.00	EA
6821	Single Boot Assembly - ATF	1.00	EA
6822	Single Boot Assembly	1.00	EA
6824	Twin Boot Assembly	2.00	EA
7876	Model 75 Extension Boot Assembly	1.00	EA
7876SS	Model 75 Extension Boot Assembly (Stainless Steel)	1.00	EA
7929	Model 90 Extension Boot Assembly	1.00	EA
9301	Model 90 30 Deg. Single Lower Boot	1.00	EA
9301SS	Model 90 30 Deg. Single Lower Boot (Stainless Steel)	1.00	EA
9302	Model 90 Lower Tandem Boot Package	2.00	EA
9305	Model 75 Lower Boot Assembly	1.00	EA
9307	Model 75 Lower Tandem Boot Package	2.00	EA
9309	Model 90 Twin Lower Boot Assembly	2.00	EA
9548	Model 90 30 Degree Two Motor Tandem Boot Assembly - Red Upper Boots	1.00	EA
9549	Model 75 30 Degree Two Motor Tandem Boot Assembly - Red Upper Boots	1.00	EA
56490SS-1	HALF,SS TWIN TNDM LWR BOOT PKG	2.00	EA