**Component Number: 7900** **Where is this used?**

| Part Number | Description | Component Quantity | U/M |
|---|---|---|---|
| 25688 | Model 125 Control Unit | 1.00 | EA |
| 27763 | International Switch With Plate Assembly | 1.00 | EA |
| 35324-1 | Dual Control Switch - 1PH-50/60HZ-220/230V | 2.00 | EA |
| 35324-2 | Dual Control Switch - 3PH-50/60HZ-220/460V | 2.00 | EA |
| 36974 | Twin Control Assembly | 1.00 | EA |
| 38605 | Model HMC 30 Degree Two Motor Tandem Boot Assembly - Red Upper Boots | 1.00 | EA |
| 38606 | Model HMC Boot Assembly | 1.00 | EA |
| 4-25866 | 45deg Discharge Head Assembly | 1.00 | EA |
| 4-38189 | 90deg Discharge Head Assembly | 1.00 | EA |
| 40169 | Model 55 Extension Boot Assembly | 1.00 | EA |
| 42288 | Model 108 Control Unit | 1.00 | EA |
| 56470 | Model 75 Plus Extension Boot Assembly | 1.00 | EA |
| 56470SS | Model 75 Plus Extension Boot Assembly (Stainless Steel) | 1.00 | EA |
| 7839 | Hopper Cover Assembly | 1.00 | EA |
| 7839SS | Hopper Cover Assembly (Stainless Steel) | 1.00 | EA |
| 7876 | Model 75 Extension Boot Assembly | 1.00 | EA |
| 7876SS | Model 75 Extension Boot Assembly (Stainless Steel) | 1.00 | EA |
| 7929 | Model 90 Extension Boot Assembly | 1.00 | EA |
| 8798 | Switch Kit | 1.00 | EA |
| 9548 | Model 90 30 Degree Two Motor Tandem Boot Assembly - Red Upper Boots | 1.00 | EA |
| 9549 | Model 75 30 Degree Two Motor Tandem Boot Assembly - Red Upper Boots | 1.00 | EA |